

Attention: Nolan.UDA

Nolan.UDA Pty Ltd
3 Bradford Street
ALEXANDRIA NSW 2015**CERTIFICATE OF ANALYSIS**

Report No:	452553083-2Z an	Date:	14 May 2015
Replacement to:	452553083-2		
Date Received:	25 June 2014	Dates Tested:	26 June 2014/28 July 2014
Purchase Order No.	140625	Method:	AS1157.2-1998-1999

Results

Sample	Growth Rating
Ultra Soft (Heavy Duty PVC Mattress Covering) (Leached)	0, 0, 0, 0
Ultra Soft (Heavy Duty PVC Mattress Covering) (Untreated)	0, 0, 0, 0
Ultra Soft (Heavy Duty PVC Mattress Covering) (Heat Treated)	0, 0, 0, 0
Silliker Control (Leached)	5, 5, 5, 5
Silliker Control (Untreated)	5, 5, 5, 5
Silliker Control (Heat Treated)	5, 5, 5, 5

Notes: 1. Leaching rate was 2 L/hr for 7 days
2. This method has been modified such that a mixed mildew fungal suspension consisting of 9 mould types was utilized in the test. (See overleaf for details).

ASSESSMENT OF GROWTH AS PER AS 1157

Fungal growth is assessed on a scale of 0-5. A rating of 0 represents complete absence of fungal growth and a rating of 5 represents complete coverage of the surface of the sample. Any trace of fungal growth, including detection under a stereomicroscope, gives a minimum assessment of 1. Assessments between 1 and 5 are based on completeness of surface coverage.

MELBOURNE20 King St Blackburn VIC 3130
Ph: 03 8878 2100 / Fax: 03 9877 8444Email: sales.au@mxns.com
www.merieuxnutrisciences.com.au

*Report No. 452553083-2Z an
Replacement to: 452553083-2*

MIXED MILDEW SPORE SUSPENSION

Silliker Australia Culture No.	Culture
13	<i>Chaetomium globosum</i> MRL 74
5	<i>Aspergillus niger</i> MRL 72
2	<i>Alternaria radicina</i> MRL 523
26	<i>Paecilomyces varioti</i> MRL 436
79	<i>Aspergillus awamori</i> MRL 519
80	<i>Penicillium corylophilum</i> MRL 1059
81	<i>Aureobasidium pullulans</i> FRR 3018
82	<i>Cladosporium resinae</i> FRR 2402
44	<i>Syncephalastrum racemosum</i> MRL 427



DAVID LIM B.Sc.,MASM,MAIFST
MICROBIOLOGIST

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s) as received. The data therefore may not be representative of the lot or batch or other samples. Consequently the data may not necessarily justify the acceptance or rejection of a lot or batch, a product recall or support legal proceedings. It is the responsibility of the client to provide all information relevant to the analysis requested. This report does not imply that Silliker Australia Pty Ltd has been engaged to consult upon the consequences of the analysis and for any action that should be taken as a result of the analysis.

TGA Licence No. MI-09022005-LI-000428-1